









# SYMBOLS






The following symbols are used in the welding Diagrams in Section RE of this manual to indicate cutting areas and the types of weld required.

SYMBOLS	MEANING	ILLUSTRATION
	<p>SAW CUT OR ROUGH CUT</p>	
	<p>REMOVE BRAZE</p>	
	<p>WELD POINTS  SPOT WELD OR MIG PLUG WELD  (See page <a href="#">IN-5</a>)</p>	
	<p>CONTINUOUS MIG WELD (BUTT WELD OR TACK WELD)</p>	
	<p>BRAZE</p>	
	<p>BODY SEALER</p>	

**Illustration of Weld Point Symbols**

**EXAMPLE:**



SYMBOL	MEANING	ILLUSTRATION	SYMBOL	MEANING	ILLUSTRATION
<p>○</p> <p>●</p> <p>●</p>	<p>Remove Weld Points</p>		<p>○</p> <p>●</p> <p>●</p>	<p>Spot Weld</p>	
<p>○</p>	<p>(Outside)</p>		<p>○</p> <p>●</p> <p>●</p>	<p>Mig Plug Weld</p>	
<p>●</p>	<p>(Middle)</p>		<p>+</p>	<p>Spot MIG Weld</p>	
<p>●</p>	<p>(Inside)</p>		<p><i>HINT: Panel position symbols are as seen from the working posture.</i></p>		